




# Number 10:



# As-built drawings of hardware can save a lot of time and money





### Number 9:



# On-site testing of possible trouble spots in the $4\pi$ installation has been essential

- Iteration was necessary to get hole pattern right for the gloveport panel
- Instrumentation Units are a critical part of the 4pi system, so we've tried to test them extensively
  - depth from pressure sensors
  - LED camera reconstuction
  - found other problems we didn't anticipate!  $\rightarrow$  Leaks
- $\cdot$  Test everything we can in advance, before  $4\pi$  installation




### Number 8:



# The pressure in the detector is affected by what goes on in the glovebox

# From Fred's talk in Tennessee: pressure measurements vs. time at lowest position




- Instantaneous "spike" followed by slow recovery to atmospheric pressure through glovebox leak.
- Need reference pressure sensor in glovebox.




### Number 7:



# The IU pressure sensor has a significant temperature dependence








### Number 6:



# The LED on the IU can't be seen by the cameras at all positions in the current camera positions






### Number 5:



# Sealing the IUs is a difficult technical challenge





- Screw enclosure with viton O-ring, threaded lucite failed
- · Pins must be glued press-fit didn't work
- What is the cause of last week's failures?
   mechanical damage? "double bubble" epoxy in LS?



### Number 4:



When you go to Japan to test things, it's better to have all the equipment prepared, tested, and shipped in advance





## Number 3:



# It is more efficient to test components extensively in the US than to have them fail in Japan







### Number 2:



### Cleaned screws must be oiled to prevent galling





Lindley: "Please remember to put a drop of some mineral oil [or LS] in the holes before assembly unless you want to cold weld the screws into the clamp and watch me cry" - Lindley




#### Number 1:



# Don't ship things to Japan by DHL

- Wednesday evening JST

   (last possible delivery time to deploy Thursday):
   still in Los Angeles
- Delivery not yet confirmed,
   5/16 2:00 pm





#### Outtakes



Alcohol can remove material from some Viton surfaces indefinitely

Glovebox leak rates have been reduced - or is it all just the rotary stage?



## Thanks!



# Thank you very much to:

- Kengo
- · Tim
- Kishimoto